


Roughness Average, Ra

 Less frequent applications

 Average application

Microinches (µin.)	63	32	16	8	4	2	1	0.5	0.25	0.125	0.063	0.032	.016	.008	.004	.0008
Micrometers (µm)	1.6	0.8	0.4	0.2	0.1	0.05	0.025	0.0125	0.0063	0.0032	0.0016	0.0008	0.0004	0.0002	0.0001	
Nanometers (nm)	1600	800	400	200	100	50	25	12.5	6.3	3.2	1.6	0.8	0.4	0.2	0.1	0.02
Angstroms (Å)	16000	8000	4000	2000	1000	500	250	125	63	32	16	8	4	2	1	0.2



Schmitt Measurement Systems, Inc.
 2765 NW Nicolai St. Portland, OR 97210
 Phone 503-227-5178 Fax 503-227-5040
<http://www.schmitt-ind.com>

084-720-001
 Last Modified on 11/15/00
 © Copyright 2000, Schmitt Industries, Inc

